

COMMISSIONER'S MONTHLY REPORT

Commissioner

Date May 3 1965  
Report for Month of April 1965

Source and Point of Measurement	Day of the Month														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	31
I. Boardman Springs #1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)															
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)															
#3. Church ditch near to heading															
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)															
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake															
II. Thomas Spring #5. Above the Olsen house below the tracks															
III. Drain #6. Drain Channel near Railroad Shop and Burningham properties															
IV. #8. Levie Ditch - Water to Church Farm, etc.															
V. #9. Pump Water at Church Welfare Farm															

Measurement 1st Date

Measurement 2nd Date

1st Measurement → 1.59 ac ft

2nd Measurement → 2.00 ac ft

2.56 ac ft

2.30 ac ft

0.0

0.0

approx - 0.115 ac ft

approx - 0.115 ac ft

approx - 0.115 ac ft

2.30 ac ft

2.56 ac ft

approx - 0.115 ac ft

0.0

0.0

0.0

Submitted by

E. Lewis Allen

\* Note 1 - all water was flowing to Utah Lake on April 15, 1965, except this 1.59 ac ft - which was flowing to P.S.C.T. & Co.

\* Note 2 - For ac ft from Boardman and 1.56 ac ft from Thomas Spring's on this date.